

Homework

- Define each of the PQCDSM parameters which are relevant for your Industry and Company.
- Ensure data recording from Cell level to plant level
- Assign accountability to specific person for updating the boards on Weekly or Monthly basis.



Implementation tasks

- Launch PQCDSM boards on any chosen Cell / Department
- Display PQCDSM board in prominent position on plant / office
- Ensure proper accountability and timely updation at every cycle (Weekly or Monthly).